Specification Of Repairs

Inspection Date 8/1/2003

Value Home Inspections, Inc. (215) 886-0010

Consultant's File No.

230483Dauphin

Consultant/Plan Reveiwer:

Catherine Hall

ID No: P0437

Borrower: Joseph A. Rapier, Jr. **Property** 2057-2061 Dauphin Street Address: Philadelphia PA 19125 Phone: (267) 973-3993 Contact Name: Joseph Rapier Contact Phone: (267) 973-3993

FHA Case #	: 0033283847				
HUD Apprai	sor:				
Appraisor's	Phone:				
Assigned Date: 8/1/2003					
Lender:	Wells Fargo Home Mortgage				
Loan No.	0033283847				

Months To Completion:

Occupied During Construction:

Not Occupied

HUD Case # 0033283847

STEP-BY-STEP PROCEDURE

- 1. The HUD accepted consultant who prepares this work write-up for an architect, engineer to home inspection service needs to inspect the property to assure: (1) That there are no rodents, termites, and other infestations: (2) that there are no defects that will affect the health and safety of the occupants: (3) the adequacy of the existing structural, heating plumbing, electrical, and roofing system: and (4) the upgrading of thermal protection (where necessary). The inspection report will be attached to the document.
- Complete each item below as necessary by either filling out the information on the work to be preformed with a brief explanation, or entering "NONE" in the "SUB-TOTAL" portion if no work is being performed in that particular subsection.
- The proposed work, and the materials used, should be explained in detail to assure a complete understanding on the required work by the contractor and the HUD authorized fee inspector. For major items (ie. kitchen cabinets, appliances, heating && air conditioning, etc.), the description or the item should enclose the make and model number (manufacturer's brochure can be attached).
- Attach a copy of any proposals from all contractors and/or subcontractors.
- Provide other drawings as necessary to assure a complete understanding of the required work by the contractor and the HUD authorized fee inspector. The following architectural exhibits are required:
 - a) A Plot Plan of the Site is required only if a new addition is being made to the existing structure. Show the location of the structure(s), walks, drives, streets, and other relevant detail. Include finished grade elevations at the property corners and building corners to assure proper drainage of water off the site. Show the required flood elevation.
 - b) Proposed Interior Plan of the Dwelling. Show where structural or planning changes are contemplated: include any addition to the dwelling.
 - c) Provide kitchen cabinet elevations, deck drawings and other exhibits as necessary to properly describe the required work. Architectural exhibits for a new addition are the same as for a newly constructed home.
- 6. Cost estimates must include labor and materials sufficient to complete the work by a contractor.
- 7. A homebuyer who would like to do any of the work must submit a letter to the lender stating his/her gualifications to perform the work in timely and workmanlike manner. If approved by the lender, the homebuyer cannot eliminate the cost estimate for labor because if the homebuyer cannot complete the work there must be sufficient money in the escrow account to get a subcontractor to do the work.
- If this is a purchase transaction and not a refinance, then attach a sales contract (the loan should go contingent upon obtaining FHA 203(k) financing).
- Transfer costs shown on the last page to the Draw Request (HUD 9746-A, VMP-436).
- Meaning of Abbreviations:

Linear foot = LF Each = Ea Square Foot = SF Lump Sum = LS Square Yard = SY * = required M = Manditory By HUD, R = Recommended By Consultant/Other, D = Desired By Homeowner

HUD Case #	
0033283847	

	1	. Mas	onry				
		TY			No. 1	70.41	This Portion Of the work will be done by:
	Level	Unit	Qty	Cost	Mark-up	Total	
Masonry: Point brick work.	D	LS	1	\$500.00	0.0%	\$500.00	Cost Estimate Attache
Remove ivy frm brick wall Siding: Replace defective siding.	D		1	\$1,250.00	0.0%	\$1,250.00	Required Repair
Replace rear wall siding with brick ven	eer to ma	tch side	wall	, ,		, ,	Permit Require
Ţ.				-Total This S	Section:	\$1,750.00	
Pror	oced w	ork an	d/or	itemized	material	s to be use	d
Borrower wants to remove all ivy from side w							
						.,	
Remove stucco, or add brick veneer over ex	ising stud	co at re	ar wali	1st floor ele	vation.		
	2	. Sidi	ng				
			La			m . 1	This Portion Of the work will be done by:
	Level	Unit	Qty	Cost	Mark-up	Total	
Siding: Replace defective siding.	D		1	\$2,500.00	0.0%	\$2,500.00	
Replace defective shingles at rear 2nd	floor					\$2,500.00	Cost Estimate Attache Required Repair
			Sub	-Total This S	Section:	\$ 2 ,500.00	Permit Require
Prop	osed w	ork an	d/or	itemized	material	s to be use	
Remove existing shingles at 2nd floor bumpo							
need to be determined prior to settlement.				<u>'</u>			
	3	Gut	tare/[Downspor	ute		
	J	. Out	1613/1	Jownspot	utə		This Portion Of the work will be
	Level	Unit	Qty	Cost	Mark-up	Total	done by:
Gutter & Downspouts: Replace bad gutters	D		1	\$400.00	0.0%	\$400.00	Owner 🗸 Contrac 🗌 Subcontra
& downspouts.			<u> </u>				Cost Estimate Attache
Extend downspout at side wall under b	rick wall	towards			241	\$400.00	Required Repair
			Sub	-Total This S	section:	Ψ-100.00	Permit Require
						s to be used	
Downspout nees to be extended under brick	path alor	ng side (of prop	erty using pv	c piping di	verting water in	to garder.
4. Roof							
4. R001							
	5	. Shu	tters				
	6	. Exte	eriors	5			
	7	. Wal	ks				
	Level	Unit	Qty	Cost	Mark-up	Total	This Portion Of the work will be done by:
Walks: other	D	l Unit	1	\$5,000.00	0.0%	\$5,000.00	Owner Contrac Subcontra
Repair/rebuild brick walk and patio at r			_ '	ψ5,000.00	0.070	ψ5,000.00	Cost Estimate Attache
Repair results stick want and patio at I	- Cui		Sub	-Total This 9	Section:	\$5,000.00	Required Repair
	Sub-Total This Section: \$5,000.00 Required Repair Permit Require						
Prop	osed w	ork an	d/or	itemized	material	s to be use	<u>d</u>
Brick patio and walkway at side of property is necessary. May cosider replacing bricks with		ed and p	oses	a tripping haz	zard. Borro	wer want to rep	air if possible, rebuild walk and patio if

HUD Case #	
0033283847	

	8	. Driv	eway	/S					
							This Portion Of the work will be		
	Level	Unit	Qty	Cost	Mark-up	Total	done bv: ☐ Owner ☑ Contrac ☐ Subcontra		
Driveways: Remove old driveway and	D		1	\$6,500.00	0.0%	\$6,500.00			
apron. Clear growth and pave front yard at fellows:	nce						Cost Estimate Attache		
Sub-Total This Section: \$6,500.00 Required Repair									
_		,					<u> </u>		
Proposed work and/or itemized materials to be used 14' wide x 20' deep concrete yard inside front yard, and 27' wide x 12' deep driveway apron at front walkway. Clear cut all overgroth, trees and evel for driveway.									
9. Painting (Ext.)									
10. Caulking									
			<u>9</u>						
	4.4								
	11	. Fen	cing						
	Level	Unit	Qty	Cost	Mark-up	Total			
Fencing: Install new fencing.	D		1	\$1,500.00	0.0%	\$1,500.00			
Install new fence with automatic remot	e control	gate					1		
			Sub	-Total This	Section:	\$1,500.00			
					_				
	12	. Gra	dina						
			<u>g</u>						
	13	. Win	dows	3					
							This Portion Of the work will be		
	Level	Unit	Qty	Cost	Mark-up	Total	done bv:		
Windows: Install new windows.	D	Ea	4	\$250.00	0.0%	\$1,000.00	Owner 🗸 Contrac 🗌 Subcontra		
New vinyl replacement windows							Cost Estimate Attache		
			Sub	-Total This	Section:	\$1,000.00	Required Repair		
							Permit Require		
					material	s to be use	<u>d</u>		
Replace windows: Double hung vinyl 3rd floo Casement window w/crar				1					
Odsement window wich	ik at zna	noor bat							
	14	. Wea	ther	strip					
	15	. Doo	rs (E	xt.)					
	Level	Unit	Qty	Cost	Mark-up	Total	This Portion Of the work will be done by:		
Doors: Install new doors	R	Ea	1	\$500.00	0.0%	\$500.00	Owner 🗹 Contrac 🗌 Subcontra		
Install kitchen door			<u> </u>	1230.00	2.07.0	+300.00	Cost Estimate Attache		
Doors: Install new doors	D	Ea	1	\$700.00	0.0%	\$700.00	Required Repair		
Replace Living Room door to garden		-					Permit Require		
_			Sub	-Total This	Section:	\$1,200.00			
Bereit	20002	orle	d / a	i+omi	matania.	a to bo	d		
	osed w	ork an	u/or	ıtemized	<u>material</u>	s to be use	<u>u</u>		
New kitchen door to yard half light New door from living room to garden custom	door to	horrowei	rs spec	cifications					

HUD Case #	
0033283847	

	16	. Doo	rs (In	it.)				
	Level	Unit	Qty	Cost	Mark-up	Total		
Doors: Install new doors	D	Ea	1	\$400.00	0.0%	\$400.00		
New swinging door to kitchen				7.00.00	515.11	7		
Doors: Install new doors	D	Ea	2	\$175.00	0.0%	\$350.00		
Closet doors (3rd floor bdrm)								
Sub-Total This Section: \$750.00								
	17	. Part	ition	Wall				
							This Portion Of the work will be	
							done bv: ☐ Owner ☑ Contrac ☐ Subcontrac	
							Cost Estimate Attache	
							Required Repair	
							Permit Require	
Prop	osed w	ork an	d/or	itemized	material	s to be used	1	
	18	. Plas	ter/D	rywall				
			La			m . 1	This Portion Of the work will be done by:	
	Level	Unit	Qty	Cost	Mark-up	Total	one bv: ☐ Owner ☑ Contrac ☐ Subcontrac	
Drywall: install new ceiling gypsum board	D	SF	150	\$6.00	0.0%	\$900.00		
Repair ceiling damage 3 areas						¢000 00	Cost Estimate Attache Required Repair	
			Sub-	Total This	Section:	\$900.00	Permit Require	
Pror	oged w	ork an	d/or	itemized	material	s to be used		
Replace damaged ceilings:	osea w	JIK an	<u> </u>	<u>rcemirzea</u>	maceriai	s to be used		
2nd floor front bdrm: 5' x 5', 2nd floor hallway	/: 5'x8', h	oles fror	n reces	ssed lights a	fter remove	ed 8'x8'		
	19	. Dec	oratir	าต				
				<u> </u>				
	Level	Unit	Qty	Cost	Mark-up	Total		
Painting: Scrape, sand smooth and paint a	D	SF	3500	\$1.75	0.0%	\$6,125.00		
min 2 coats of good quality paint at all exterior woodwork and metal.								
Prep and prime al rooms/areas at 2nd	and 3rd f	loors						
			Sub-	Total This	Section:	\$6,125.00		
	20	. Woo	d Tri	m				
	21	. Stai	re					
		. Otai	13				This Portion Of the work will be	
	Level	Unit	Qty	Cost	Mark-up	Total	done bv:	
Stairs: Install carpet and pad (per riser)	D	Ea	12	\$25.00	0.0%	\$300.00	Owner Contrac Subcontrac	
Replace carpeting at rear steps to 2nd	floor						Cost Estimate Attache	
Stairs: Provide hand rails, etc.	D	LF	45.	\$100.00	0.0%	\$4,500.00	Required Repair	
Replace new hadrail entire length 45 ft				Total This		******	Permit Require	
		\$4,800.00						
Prop	osed w	ork an	d/or	itemized	material	s to be used	<u>1</u>	
Install new wood handrails front first to third	floor-cust	om woo	d railin	g with decor	ative posts	per borrowers	specifications	

HUD Case #	
0033283847	

	22	. Clos	ets				
	T1	11	04	C4	M1	T-4-1	
	Level	Unit	Qty	Cost	Mark-up	Total	
Doors: Install new doors	D 0 0 1	Ea	3	\$200.00	0.0%	\$600.00	
Sliders (set) for closets in 2nd floor bdr	m-2, 3ra	tioor ba		Total This	O a ati a mu	\$600.00	
			Sub-	Total This	Section:	\$600.00	
	23	. Woo	d Flo	ors			
							This Portion Of the work will be
	Level	Unit	Qty	Cost	Mark-up	Total	done bv:
Wood Floors: Sand, fill and refinish hardwood floors.	D	SF	745	\$5.00	0.0%	\$3,725.00	Owner Contrac Subcontrac
Finish floors at Liv Rm, Din Rm, 1st flo	or hallwa	ıy					Cost Estimate Attache Required Repair
			Sub-	Total This	Section:	\$3,725.00	Permit Require
Prop	osed w	ork and	d/or	itemized	material	s to be used	<u>1</u>
Finish flooring: Living Room 28' x 9' Dining Room 15' x 10.5' 1st fl Hall 22.5' x 3.25'							
	24	. Fini	shed	Floors			
							_
	Level	Unit	Qty	Cost	Mark-up	Total	
Finish Floors: Install vinyl tile or sheet goods with 1/4" underlayment at:	R	SF	160	\$8.00	0.0%	\$1,280.00	
Kitchen and 2nd floor bath							
			Sub-	Total This	Section:	\$1,280.00	
	0.5						
	25	. Cera	amic	Tile			
	Level	Unit	Qty	Cost	Mark-up	Total	This Portion Of the work will be done by:
Ceramic Tile: Replace defective tile in bath.	R	SF	30	\$30.00	0.0%	\$900.00	Owner 🗸 Contrac 🗌 Subcontrac
3rd floor bath walls	- 1	OI .	00	Ψ00.00	0.070	ψοσσ.σσ	Cost Estimate Attache
ora noor baan wane			Sub-	Total This	Section:	\$900.00	Required Repair
							Permit Require
Prop	osed w	ork and	d/or	itemized	material	s to be used	1
Install ceramic tile on bathroom walls over ne	ew moist	ure-resis	tant wa	allboard. Tile	e cost up to	\$6.00 sf.	
26. Bath Accessories							
							This Portion Of the work will be
	Level	Unit	Qty	Cost	Mark-up	Total	done by:
Bath Accessories: Install medicine cabinet in bath.	D		2	\$310.00	0.0%	\$620.00	Owner Contrac Subcontrac
Surrface mounted at both baths							Required Repair
			Sub-	Total This	Section:	\$620.00	Permit Require
Prop	osed w	ork and	d/or :	itemized	material	s to be used	1
Cost of cabinet up to \$200.00							

HUD Case #	
0033283847	

	27	. Plur	nbing	9				
	× ,	TT	Lou		26.2	75 4 1	This Portion Of the work will be done by:	
	Level	Unit	Qty	Cost	Mark-up	Total	Owner Contrac Subcontrac	
Plumbing: Bath sink w/vanity	R	Ea	2	\$550.00	0.0%	\$1,100.00		
2nd floor, 3rd floor							Cost Estimate Attache	
Plumbing: Install new hot & cold water piping.	R		3	\$400.00	0.0%	\$1,200.00	☐ Required Repair ☐ Permit Require	
2nd floor bath , 3rd floor bath, kitchen								
Plumbing: Install new kitchen sink.	R		1	\$600.00	0.0%	\$600.00		
Drop -in sink in counter								
Plumbing: Replace defective bath faucet.	R		4	\$350.00	0.0%	\$1,400.00		
all baths								
Plumbing: other	R	LS	4	\$300.00	0.0%	\$1,200.00		
Remove and disconnect all existing plubdroom	ımbing liı	nes at a	ll baths	, kitchen, 3rd	d floor			
Plumbing: Replace defective kitchen faucet.	R		1	\$500.00	0.0%	\$500.00		
Cost of faucet of to 300.00								
Plumbing: Replace defective sewer lines.	R	LF	20.	\$65.00	0.0%	\$1,300.00		
Replace 20 ft cast iron piping at basen	nent w/ p	vc						
Plumbing: Vinyl tub enclosure 3/5 piece complete	D	Ea	1	\$600.00	0.0%	\$600.00		
2nd floor bath, cost of enclosure up to	\$300.00	(include	s nece	ssary wall pr	rep)			
Plumbing: other	R	LS	1	\$3,000.00	0.0%	\$3,000.00		
Replace existing lead incoming water I 3/4 "	ine from	meter to	street	connection	w/ copper			
All sink installations including trap and drain All hot and cold water piping including shut or Replace faucets provides a cost for faucet at Removal and capping plumbing lines at 3rd facet.	lines off valves ssembly	at lines up to \$2	00 eac	h.		s to be used		
	28. Electrical							
		** **	Lou		24.1		This Portion Of the work will be done by:	
	Level	Unit	Qty	Cost	Mark-up	Total	Owner Contrac Subcontrac	
Electrical: Install 100 amp service.	R		1	\$750.00	0.0%	\$750.00		
Electrical: Add ground fault interrupt outlet	R	Ea	6	\$150.00	0.0%	\$900.00	Cost Estimate Attache	
at wet areas	soment f	or louds	,				Required Repair	
all baths, kitchen, rear wall at patio, ba	D	Ea	12	\$80.00	0.0%	\$960.00	Permit Require	
Bdrms, Liv Rm at locations indicated b			12	ψου.σο	0.070	Ψ000.00		
Electrical: Ceiling fan/light	D	Ea	6	\$600.00	0.0%	\$3,600.00		
Cost of fan/light up to \$300 each (inclu					0.070	ψο,σσσ.σσ		
Electrical: Other	D	Ea	1 1	\$300.00	0.0%	\$300.00		
					0.070	Ψ000.00		
Remove all wiring and recessed light fill Electrical: Other	D D	Ea	1	\$750.00	0.0%	\$750.00		
Chandelier at living room cost for fixtur			<u>'</u>	Ψ700.00	0.070	Ψ700.00		
Electrical: Install three (3) way switch.	R	500.	3	\$400.00	0.0%	\$1,200.00		
Connect all hallway lighting at both cor		loore for		1		Ψ1,200.00		
Some an hanway lighting at both cor	iiicoleu II	10013 101		·Total This		\$8,460.00		
Dror	oged	ork an			_	s to be used	3	
Hall lighting w/three way switch- cost for light							4	
I lan ngriting with the way switch took for light	c include (I	iot odilli	·9 ·ai/i	·9··ι·/ up ιο ψ	.50.00 Cac			

HUD C	ase #
00332	83847

	20	L!a-	din -				
	29	. Hea	ting				
	Laval	T1:4	Otro	Cost	Moult un	Total	This Portion Of the work will be done by:
	Level	Unit	Qty	Cost	Mark-up	Total	Owner Contrac Subcontrac
Heating: Other	R		1	\$1,500.00	0.0%	\$1,500.00	
Heating repair/servicing and adding a	central hu	umidifier					Cost Estimate Attache
			Sub	-Total This S	Section:	\$1,500.00	Required Repair
							Permit Require
						s to be use	
Heater to be cleaned, serviced and repaired Installation of humidifier on main unit with hu							- including duct cleaning for all floors
	maiotat	oona or v	mod to	o damo lo dati	011 01 010111	iootat.	
	30	. Inst	ılatio	n			
	31	. Cab	inetr	у			
				_			This Portion Of the work will be
	Level	Unit	Qty	Cost	Mark-up	Total	done bv:
Cabinetry: Base and wall cabinets:		LS	1	\$8,000.00	0.0%	\$8,000.00	Owner 🗸 Contrac 🗌 Subcontrac
Designed per borrower specification for	r materia	ls and lo	ocation	1			Cost Estimate Attache
Cabinetry: Kitchen countertop.	R		16	\$75.00	0.0%	\$1,200.00	Required Repair
Top quality laminate counter top per li	ner feet o	cost per	ft of co	ounter top \$4	0		Permit Require
			Sub	-Total This S	Section:	\$9,200.00	
Pror	oosed w	ork an	d/or	itemized	material	s to be use	3
Counter top includes 4 " backsplash, field me						s co be use	<u> </u>
Counter top includes 4 backspiash, held the	casarca	aria srio	p-built	by labilicators			
	32	. App	lianc	es			
	Level	Unit	Qty	Cost	Mark-up	Total	
Appliances: Disposal	R	Ea	1	\$450.00	0.0%	\$450.00	
Cost of unit >\$275.							
Appliance: Dishwasher	D	Ea	1	\$750.00	0.0%	\$750.00	
Cost of unit >\$500				1 04 400 00	0.00/		
Appliances: Range	R	Ea	1	\$1,400.00	0.0%	\$1,400.00	
Cost of unit >\$1100						•••••	
			Sub	-Total This S	Section:	\$2,600.00	
	33	. Bas	emer	nts			
	Level	Unit	Qty	Cost	Mark-up	Total	
Basement: Repair/repace damaged	R	Ea	1	\$500.00	0.0%	\$500.00	
steps/stringers/supports Replace vertical support for stair string	iers						
Basement: Repair/sister damaged	R	LF	5	\$50.00	0.0%	\$250.00	
joists/beams/sub-flooring							I
1 cut beam at rear of basement							
			Sub	-Total This S	Section:	\$750.00	

HUD Case # 0033283847

34. Cleanup

	Level	Unit	Qty	Cost	Mark-up	Total
Cleanup: Remove debris from property exterior			1	\$2,000.00	0.0%	\$2,000.00
Includes dumpster and debris removal from landscaping activies						
Cleanup: Remove debris from property	R		1	\$1,500.00	0.0%	\$1,500.00
interior						

Incudes debris removal from window replacement and bath/kitchen remodeling

Sub-Total This Section: \$3,500.00

35. Miscellaneous

RECAP SUBTOTALS

Construction Sub-Totals

\$1,750.00 1. Masonry \$2,500.00 2. Siding 3. Gutters/Downspouts \$400.00 4. Roof \$0.00 5. Shutters \$0.00 6. Exteriors \$0.00 7. Walks \$5,000.00 \$6,500.00 8. Driveways 9. Painting (Ext.) \$0.00 10. Caulking \$0.00 \$1,500.00 11. Fencing 12. Grading \$0.00 13. Windows \$1,000.00 \$0.00 14. Weatherstrip 15. Doors (Ext.) \$1,200.00 \$750.00 16. Doors (Int.) 17. Partition Wall \$0.00 18. Plaster/Drywall \$900.00 \$6,125.00 19. Decorating 20. Wood Trim \$0.00 \$4,800.00 21. Stairs 22. Closets \$600.00 23. Wood Floors \$3,725.00 \$1,280.00 24. Finished Floors 25. Ceramic Tile \$900.00 \$620.00 26. Bath Accessories 27. Plumbing \$10,900.00 28. Electrical \$8,460.00 29. Heating \$1,500.00 30. Insulation \$0.00 31. Cabinetry \$9,200.00 \$2,600.00 32. Appliances 33. Basements \$750.00 34. Cleanup \$3,500.00 35. Miscellaneous \$0.00

Construction Cost Subtotal:

\$76,460.00

Allowable Fees & RecapTotals

HUD Case #	
0033283847	

CONSULTANT'S COMMENT			
	SIGNATURES		
Date of Final Acceptance:			
Consultant/Plan Reveiwer: <u>Cathericae L.</u>	### Date: 8/18/2003 ID No P0437		
Borrower(s):	Date:		
General Contractor:	Date:		